IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No	7,115,532 B2
Patent Issue Date	
Application Serial No	10/655,997
Filing Date	September 5, 2003
Assignee	Micron Technology, Inc.
Inventorship	Jon P. Daley
Attorney's Docket No	MI22-2380
Title: Methods of Forming Patterned Photoresist layers Over Semiconductor Substrates	

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR APPLICANT MISTAKES and PTO MISTAKES (37 C.F.R. §§ 1.322(a) and 1.323)

To:

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

ATTN:

Decision and Certificate of Correction

Branch of the Patent Issue Division

From:

Mark S. Matkin (Tel. 509-624-4276; Fax 509-838-3424)

Wells St. John P.S.

601 W. First Avenue, Suite 1300

Spokane, WA 99201-3828

Sir:

It is hereby requested that a Certificate of Correction be issued with respect to Patent No. 7,115,532 B2, granted October 3, 2006, in accordance with the Certificate of Correction form attached hereto.

It is noted that errors appear in this patent of a typographical nature of character, as more fully described below. The errors occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination.

Other errors listed on the Certificate of Correction form were apparently incurred through the fault of the PTO as will be disclosed by the records of files in the Office.

Attached hereto, is Form PTO-1050, being suitable for printing.

The exact page and line number where the errors occur in the application file are:

Page 15, paragraph 33;

On the Form PTOL-085B filed August 21, 2006 in Section 3, Assignee Name and

Residence Data to be Printed on the Patent.

The Director is hereby authorized to charge the \$100.00 fee as required under 37 CFR 1.20(a), or credit any overpayment, to Deposit Account No. 23-0925.

Respectfully submitted,

Dated: 7 - 12 - 07

Mark S. Matkin

Reg. No. 32,268

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 7,115,532 B2

DATED

: October 3, 2006

INVENTOR(S)

: Daley

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title Page, Assignee:, please delete "Technolgoy" after "Micron" and insert -- Technology--.

Title Page 2, OTHER PUBLICATIONS, please delete "10/882,118" after "No." and insert --10/822,118--.

Col. 4, line 26, please delete "the, outer" before "surface" and insert -- the outer ---.

Col. 6, line 21, please delete "wherein" after "means" and insert --herein--.

Col. 8, line 38, claim 46, please delete "1" after "claim" and insert --29--.

Col. 8, line 42, claim 47, please delete "1" after "claim" and insert --29--.

Col. 8, line 48, claim 49, please delete "1" after "claim" and insert --29--.

Page 1 of 1

Mailing Address of Sender:

Mark S. Matkin Wells St. John P.S. 601 West First Avenue, 3

601 West First Avenue, Suite 1300 Spokane, WA 99201-3828

Patent No. <u>7,115,532 B2</u>

S:\M122\2380\COC.doc